

Malmesbury Town Council – Planning and Environment committee

Condition survey of Malmesbury Town Council owned bins

Location	Condition Good (G) Fair (F) Poor (P)	If fair or poor, please describe the problem
Kings Wall	G	
St Aldhelms Mead Dog waste bin	G	
St Aldhelms Mead play area	P	Rusty – all paint flaking off. Lock not great.
Cloisters	G	
Mill Lane	G	
Burnivale	G	
Activity Zone	G	
Horsefair	G	
Foundry Road	G	
White Lion Park 5 bins	G X 4 P X 1	This bin ready for replacing. Not much capacity and bottom is rusting out.
Football Club	G	
Tetbury Hill	G	
Bloor Homes 2 bins	G X 1 P X 1	Needs replacing – liner is broken and outer casing is split.
Cemetery 5 bins	G X 5	
Reeds Farm	G	But not much capacity and would benefit from replacing with larger bin.
Station Yard	P	Cast iron – lock doesn't work and is dangerous
Market Cross	P	Cast iron – poor condition and appearance*
Cross Hayes by library	P	No door lock
Cross Hayes by Town Hall	F	Cast iron. Too small, larger bin reqd
Cross Hayes by Town Hall	F	Cast iron. Too small, larger bin reqd
Cross Hayes by Bertie B's	P	Cast iron. Too small, larger bin reqd
Botton Back Hill steps	P	Cast iron. Too small, larger bin reqd
High Street	P	Cast iron. Too small, larger bin reqd
All locks on cast iron bins worn.. some do not lock.		

Location of Malmesbury Town Council bins that are missing (no longer in situ)

Cuckingstool Mead – 1 bin missing
Park Road – 1 bin missing
Riverside – 1 bin missing

Please note there is £3,300 ear marked 'bins' this year.

Lisa Dent
Deputy Town Clerk
August 2024

* Market Cross cast iron bin

